

NO: 21-16-98

SUBJECT: Revised Front Band Adjustment For 42RE Transmissions

DATE: Dec. 4, 1998

NOTE: THIS INFORMATION APPLIES TO VEHICLES EQUIPPED WITH A 42RE TRANSMISSION.

DISCUSSION:

The final adjustment for the front band has been changed to 3 turns. Whenever performing this adjustment on a 1999 model 42RE transmission, be sure to only back off the adjusting screw 3 turns prior to torquing the lock nut. All other steps of the procedure are unchanged.

Service manual revision pages will be sent at a later date to address this change.

POLICY: Information Only