

**NO: 08-20-99**

**SUBJECT: Revised Sun Roof Express Open Position**

**DATE: June 18, 1999**

**DISCUSSION:**

1999 vehicles equipped with a sunroof contained an express open position feature. This feature limited the sunroof travel to stop approximately 4 inches before the full open position when the switch was depressed for less than one second. This position allowed the sunroof to operate at the quietest position relative to wind noise. This feature could be overridden by depressing the open switch a second time, which would open the window fully.

Effective with vehicles built after April 15, 1999 (MDH 0415XX), the ability to override the express open position will no longer be available. A permanent stop is now in place, which prevents the window from opening to the full open position regardless of switch operation. This also applies to MOPAR replacement parts manufactured after April 15, 1999. No attempts should be made to repair this condition.

**POLICY: Information Only**